

# Suspended Solid Conversion Table

<b>PPM</b>	<b>%</b>	<b>LBS./ 1000 GAL.</b>
10,000	1.000	80.0
8,000	.8000	70.0
6,000	.6000	50.0
4,000	.4000	35.0
2,000	.2000	15.0
1,000	.1000	9.0
800	.0800	6.5
600	.0600	5.5
400	.0400	3.5
200	.0200	1.75
100	.0100	.85
80	.0080	.65
60	.0060	.50
40	.0040	.35
20	.0020	.175
10	.0010	.08
8	.0008	.065
6	.0006	.055
4	.0004	.035
2	.0002	.0175
1	.0001	.0003